Monterey, Smokehouse
State Road 423, .7 miles east of Route 13
St. Georges Hundred
McDonough vicinity
New Castle County
Delaware

HABS No. DE-207-C

HABS No. DE-207-C

HABS No. DE-207-C

ABS No. DE-207-C

HABS No. DE-207-C

## PHOTOGRAPH

WRITTEN HISTORICAL AND DESCRIPTIVE DATA
REDUCED COPIES OF MEASURED DRAWINGS

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, DC 20013-7127

Form 10-920 (June 1983)

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS DEL, 2-McDo.V 1-C-

## ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VIC	YTINK	
DELAWARE	NEW CASTLE		MCDONOUGH VICINITY		
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)				HABS NO.	
MONTEREY, SMOKEHOUSE			DE-207-C		
SECONDARY OR COMMON NAMES OF S	SECONDARY OR COMMON NAMES OF STRUCTURE				
COMPLETE ADDRESS (DESCRIBE LOCA	TION FOR RURAL	SITES)			
State Road 423, .7 miles east of Route 13, St. Georges Hundred					
DATE OF CONSTRUCTION (INCLUDE SOURCE)  ARCHITECT(S) (INCLUDE SOURCE)			1		
c. 1854					
SIGNIFICANCE (ARCHITECTURAL AND	HISTORICAL, INC	LUDE ORIGINAL USE	OF STRUCTUR	E)	
STYLE (IF APPROPRIATE)					
TATERIAL OF CONSTRUCTION (INC.)	OF STRUCTURAL	CVCTEMOL II. 11			
MATERIAL OF CONSTRUCTION (INCLU- with seven rows of stretchers	s to one row c	of headers. Roof	re of brick is pyramida	laid in common bond, al. with plaster on	
the interior. SHAPE AND DIMENSIONS OF STRUCTU					
See measured drawings.	KE ISKETCHED I L	UUN PLANS ON SEFAI	TA IE PAUES AI	1E ACCEPT ADLES	
EXTERIOR FEATURES OF NOTE Decor	rative bargebo atop the cupo	ards are suspende la (ventilator)	ed from the as is commor	pyramidal roof. A	
outbuildings on the Monterey	estate.	, , , , , , , , , , , , , , , , , , ,			
The state of NOTE (DECO)	7:25 5: 00B BL 4M	C C MOT OVETOUED			
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) There are two separate levels (each with exterior entrances): a subterranean room, and the smokeroom itself. In the					
latter are forged hooks for h	nanging meats,	and whitewashed	walls and p	lastered ceilings.	
			<del></del>	· · · · · · · · · · · · · · · · · · ·	
MAJOR ALTERATIONS AND ADDITIONS construction. However, within				to any additional	
there exists a fitting for a					
structure's original use.					
PRESENT CONDITION AND USE Walls	, bargeboards	, and cupola in $\epsilon$	advanced sta	te of decay.	
Presently abandoned; formerly	r a storage bu	11ding.		· ;	
OTHER INFORMATION AS APPROPRIAT	ΓE				
SOURCES OF INFORMATION (INCLUDIA			TATE REGISTE	RS, ETC.)	
Beers, D.G. Atlas of the Sta	te of Delawar	e, 1868.			
National Register of Historic	Places				
COMPILER, AFFILIATION Penny Scha	ffer, Center	for Historic Arch	itecture	DATE 5/22/86	
and Engineering, University o					